


New Durham Meeting House
New Durham, New Hampshire

Historic Building Assessment
with
Preservation Guidelines



Prepared by

Stephen Bedard
Bedard Preservation & Restoration

and

Elizabeth Durfee Hengen
Preservation Consultant

with

Sarah Dangelas Hofe
Historian

for

Town of New Durham

February 2009

New Durham Meeting House
Historic Building Assessment with Preservation Guidelines

TABLE OF CONTENTS

Introduction.....	1
History and Evolution of the Meeting House	3
Additional Maps, Plans and Images of the Meeting House	21
New Durham Meeting House Timeline.....	26
Architectural Description and Surviving Character-Defining Features	27
Existing Conditions Survey.....	47
Site	47
Foundation	47
Structural Systems	47
Exterior Architectural Elements	50
Interior Architectural Elements.....	51
Mechanical & Electrical Systems	55
ADA.....	55
Preservation Guidelines for Needed Work.....	56
Overall Approach to Treatment	56
Work Phases.....	56
On-Going Schedule of Maintenance.....	59
Potential Future Uses.....	60
Appendices	
A: Secretary of Interior's Standards for Preservation.....	61
B: Measured Drawings	62

Cover image: New Durham Meeting House, ca. 1880- 1892. *Collection of New Hampshire Historical Society*